	ROOM #	SAMPLE TYPE	ROOM TYPE	SURFACE	SAMPLE DATE	DETECTED	AROCLOR FOUND	LEVEL (ug/100cm2)	ABOVE EPA LEVEL (10 ug/100cm2)?	RESULTS PAGE #	DUPLICATE	MISC NOTES
1	100	Wipe	Maintanence Utility	Desk	Dec 2023	yes	1262	1.95	No	Page 100		
1	101	Wipe	Maintanence Utility	Lid	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	102A	Wipe	Lab	Desk	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	103	Wipe	Lab	Desk	Dec 2023	Yes	1262	7.4	No	Page 100		
1	103B	Wipe	Lab	Vent	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	116	Wipe	Maintanence Utility	Desk	Dec 2023	Yes	1262	1.12	No	Page 100		
1	117	Wipe	Lab	Table	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	117 (DUP)	Wipe	Lab	Table	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	120	Wipe	Classroom	Desk	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	125	Wipe	Maintanence Utility	Lid	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	127	Wipe	Maintanence Utility	Metal box	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	130	Wipe	Maintanence Utility	Table	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	197	Wipe	Elevator	Elevator buttons	Dec 2023	No	Below RL	Below RL	No	Page 100		
1	198	Wipe	Elevator	Elevator buttons	Dec 2023	Yes	1262	0.592	No	Page 100		
1	199	Wipe	Elevator	Elevator buttons	Dec 2023	yes	1262	0.573	No	Page 100		
2	201	Wipe	Bathroom	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 173		
2	202 (DUP)	Wipe	Classroom	Table	Dec 2023	No	Below RL	Below RL	No	Page 100	Yes (2 samples taken both below RL)	
2	204E	Wipe	NO DATA	NO DATA	NO DATA	NO DATA	NO DATA	NO DATA	NO DATA	Page 51		Listed as sample site, but no data
2	208Q	Wipe	Office	Desk	Dec 2023	No	Below RL	Below RL	No	Page 100		Not listed as a sample site on Geosyntec report page 51
2	210	Wipe	Classroom	Desk	Dec 2023	No	Below RL	Below RL	No	Page 170	No	
2	213	Wipe	Bathroom	Counter	Dec 2023	Yes	1262	0.673	No	Page 169	No	Just outside? Odd placement of dot (just outside bathroom)
2	216	Wipe	Classroom	Desk		No	Below RL	Below RL	No	Page 171	No	
2	218	Wipe	Classroom	Desk	Dec 2023	Yes	1262	0.644	No	Page 168	No	
2	220	Wipe	Classroom	Vent	Dec 2023	Yes	1262	9.49	No	Page 167	No	
2	222	Wipe	Maintenance/Utility Room	Product despenser	Dec 2023	Yes	1262	0.733	No	Page 166	No	
3	300D	Wipe	Office	Window sill	Dec. 2023	Yes	1262	74.6	Yes	Page 101	No	
3	309	Wipe	Bathroom	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
3	310L	Wipe	Office	Vent	Dec. 2023	Yes	1262	1.87	No	Page 162	No	
3	310P	Wipe	Office	Window Sill	Nov. 2023	Yes	1262	1.3	No	Page 811	No	
3	310P	wipe	Office	Wall	Nov. 2023	Yes	1262	1.3	No	Page 811	No	
3	310Q	Wipe	Office	Window Sill	Nov. 2023	Yes	1262	1.1	No	Page 811	No	
3	312	Wipe	Classroom	Table	Dec. 2023	Yes	1262	0.529	No	Page 101	--	
3	312 (DUP)	Wipe	Classroom	Table	Dec. 2023	No	Below RL	Below RL	No	Page 101	Yes	
3	313	Wipe	Maintenance/Utility Room	Shelf	Dec. 2023	Yes	1262	0.763	No	Page 101	No	
3	325	Wipe	Bathroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
3	326S	Wipe	Office	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
4	400	Wipe	Classroom	Desk	Dec 2023	Yes	1262	1.57	No	Page 101	No	
4	402G	Wipe	Office	Window Sill	Dec 2023	Yes	1262	7.75	No	Page 101	No	
4	406	Wipe	Bathroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
4	412G	Wipe	Office	Microwave	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
4	413	Wipe	Maintenance/Utility Room	Shelf	Dec 2023	yes	1262	1.43	No	Page 101	No	
4	414A	Wipe	Classroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
4	417A	Wipe	Lab	Window Sill	Nov 2023	Yes	1262	8.5	No	Page 811	No	
4	417B	Wipe	Lab	Window Sill	Nov 2023	Yes	1262	6.2	No	Page 811	No	
4	419	Wipe	Bathroom	Shelf	Dec 2023	Yes	1262	3.1	No	Page 101	No	
4	424	Wipe	Classroom	Desk	Dec 2023	Yes	1262	0.766	No	Page 101	No	
5	500	Wipe	Classroom	Window Sill	Dec 2023	Yes	1262	4.5	No	Page 101	No	
5	509	Wipe	Bathroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
5	510E	Wipe	Office	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
5	514	Wipe	Maintenance/Utility Room	Product despenser	Dec 2023	Yes	1262	1.62	No	Page 101	No	
5	518	Wipe	Office	Printer	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
5	519	Wipe	??	??	Nov 2023	No	Below RL	Below RL	No	Page 811		
5	519E	Wipe	Office	Window Sill	Nov 2023	No	Below RL	Below RL	No	Page 811	No	
5	520E	Wipe	Office	Window Sill	Nov 2023	No	Below RL	Below RL	No	Page 811	No	
5	526	Wipe	Bathroom	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
5	528	Wipe	Office	Window Sill	Nov 2023	No	Below RL	Below RL	No	Page 811	No	
5	529	Wipe	Classroom	Vent	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
5	532	Wipe	Classroom	Table	Dec 2023	No	Below RL	Below RL	No	Page 101	No	
6	604	Wipe	Lab	Table	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
6	605	Wipe	Lab	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
6	607	Wipe	Bathroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
6	608P	Wipe	Office	Desk	Dec 2023	Yes	1262	2	No	Page 102	No	
6	613	Wipe	Maintenance/Utility Room	Cardboard box	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
6	616A	Wipe	Office	Window Sill	Dec 2023	Yes	1262	1.91	No	Page 102	No	
6	630	Wipe	Bathroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
7	700	Wipe	Lab	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
7	719	Wipe	Bathroom	Counter	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
7	729	Wipe	Office	Book	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
7	730	Wipe	Office	Window Sill	Nov 2023	Yes	**1262**/1254	122.3	**Yes**	Page 811	No	
7	732C	Wipe	Office	Window Sill	Nov 2023	Yes	1262	1.8	No	Page 811	No	
7	734	Wipe	Maintenance/Utility Room	Shelf	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
7	742	Wipe	Lab	Window Sill	Dec 2023	Yes	1262	0.573	No	Page 102	No	
7	744	Wipe	Bathroom	Product despenser	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
7	761	Wipe	Office	Desk	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
Roof	P1000A	Wipe	Maintenance/Utility Room	Desk	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
Roof	P1001A	Wipe	Maintenance/Utility Room	Book	Dec 2023	No	Below RL	Below RL	No	Page 102	No	
Roof	P1003	Wipe	Maintenance/Utility Room	Book	Dec 2023	Yes	1262	7.88	No	Page 102	No	
Roof	P1004	Wipe	Maintence/Utility Room	Metal Box	Dec 2023	Yes	1262	2.87	No	Page 102	No	

SOURCE DOCUMENT: https://www.ncsu.edu/poe-hall/updates/updates/2024/06/poe-hall-second-phase-testing-report-is-available/

LOQ=Limit of Quantification, results were below the limit of sensitivity of the lab method

NM = Not Measured

N/A = Not Available

RL = Reporting Limit

NS = No Sample

DUP = Duplicate

Nov 2023 = Sample taken prior to Poe Hall's closure

Sample that scored above EPA level (10 ug/100 cm2)

Duplicate Sample

Sample with MISC notes

	ROOM #	SAMPLE TYPE	ROOM TYPE	SURFACE	SAMPLE DATE	DETECTED	AROCLOR FOUND	LEVEL (ug/100cm2)	ABOVE EPA LEVEL (10 ug/100cm2)?	RESULTS PAGE #	DUPLICATE	MISC NOTES
Sample scored above EPA level AND taken in Nov. 2023												